



## Tip of the Week – Preventing Risk



### **CASE STUDY #43** PaSea H.EL.M.E.T. Marine Risk Assessment

**RISK ELEMENT:** Lifebuoys, Life Jackets and Immersion Suits

**MRA FINDING:** The lights of the immersion suits had expired and spare lights did exist onboard.

**REF. SOLAS III/7, 20, 32, LSA II/2**

**THIS IS A CLEAR INDICATION THAT THE INSPECTION OF LIFE SAVING APPLIANCES WAS NOT CARRIED OUT PROPERLY AND WITH THE REQUIRED CAUTION.**

**IN SUCH CASES A RELEVANT REQUISITION NEEDS TO BE FORWARDED BY THE CREW TO THE OPERATORS FOR NEW LIGHTS TO BE PROVIDED AT THE NEXT PORT OF CALL.**

**OPERATORS NEED TO RAISE AWARENESS LEVELS BY CREW MEMBERS ON SUCH MATTERS BECAUSE, SAFETY IS FIRST**

## **Making Prevention A HABIT!**